

GALLATIN**SUMNER CO RGNL** (M33) 2 E UTC-6(-5DT) N36°22.51' W86°24.51'

583 B NOTAM FILE BNA

RWY 17-35: H6300X100 (ASPH) S-45, D-96 MIRL 0.8% up N

RWY 17: REIL. PAPI(P2L)—GA 3.0° TCH 33'. Trees.

RWY 35: REIL. PAPI(P2L)—GA 3.0° TCH 37'. Tree.

SERVICE: S4 **FUEL** 100LL, JET A **OX 1 LGT** Rwy 17 PAPI unusable
byd 5° right of centerline due to obstacles. **ACTIVATE MIRL** Rwy
17-35—CTAF.**AIRPORT REMARKS:** Attended 1300-0100Z†.**AIRPORT MANAGER:** (615) 452-7248**WEATHER DATA SOURCES:** AWOS-3 132.725 (615) 230-8005.**COMMUNICATIONS:** CTAF/UNICOM 123.05Ⓡ **NASHVILLE APP/DEP CON** 118.4**GCO** 135.075 (BNA CLNC DEL, if unable, for CLNC DEL ctc BNA Apch
at 615-695-4522)**RADIO AIDS TO NAVIGATION:** NOTAM FILE BNA.**NASHVILLE (H) VORTAC** 114.1 BNA Chan 88 N36°08.22'
W86°41.09' 045° 19.6 NM to fld. 566/2W.

VORTAC unusable:

062°-069° blo 6,000'

ST LOUIS
H-6K, 9A, L-16J
IAP